



National Preservation Institute

P.O. Box 1702 Alexandria, VA 22313-1702 703.765.0100 info@npi.org www.npi.org

Karen Van Citters, CSI, CDT

Contact Information:

Principal, Van Citters Historic Preservation, LLC, 410 Amherst Dr. SE, Albuquerque, NM 87106
505.268.1324, karen@vcpreservation.com, www.vcpreservation.com

Education:

M.Arch., University of New Mexico, 1997

M.S., historic preservation, Columbia University, 1987

B.A., environmental design, University of New Mexico, *Cum Laude*, 1985

36 CFR 61 Appendix A-qualified as an architectural historian and historical architect

Experience:

- Project management for interdisciplinary cultural resource projects
- National Register evaluation of buildings and structures
- HABS/HAER documentation of historic structures
- Historic structures reports
- Maintenance and preservation plans for historic properties
- Conditions assessments and recommendations for repair
- Compliance with regulatory processes/preservation standards
- Development of cultural resource management databases
- Creative mitigation of historic properties
- National Historic Preservation Act, Section 106 process
- Secretary of the Interior's Standards (Identification and the Treatment of Historic Properties)

Selected Projects:

- Draft preservation plan, including cultural landscapes, New Mexico State University, Las Cruces, NM
- Preservation plan, Camp Pinchot and Georgia Avenue housing area, Eglin Air Force Base, FL
- Preservation plan, including cultural landscapes, University of New Mexico Main Campus, NM
- Preservation plan, Talihina Historic District, Indian Health Service, OK
- Preservation plan, Schurz, Indian Health Service, NV
- Specifications for repair of vigas, wood windows, and other wood elements, National Park Service, Old Santa Fe Trail Building (National Historic Landmark), Santa Fe, NM
- Conditions assessment and recommendations for emergency repair, Wheelock Academy (NHL), OK
- Historic structure report, Lake McDonald Lodge (NHL), Glacier National Park, MT
- Measured drawings and structural repair coordination, New York Stock Exchange (NHL), NY
- Historic structure report, Henry C. Trost's YMCA Building, New Mexico State University, NM

Professional Affiliations:

Construction Specifications Institute; Institute of Transportation Engineers; National Trust for Historic Preservation; Transportation Research Board, CSS Task Force